



Maintenance Next Due Report

Log Date -- 03 Sep 2014

Include only mandatory service information not yet accomplished

Projected Through:

11170 Hours TT
11658 Landings

11 Dec 2014 Date

N35BG

Current TT 10990.0
Current Lndgs 11478
Current Hr Mtr 10990.0

Phone: 303-745-5588 FAX: 303-745-1507

Aircraft Make Learjet
Aircraft Model 35A
Aircraft Serial No. 35-402
Airworthiness Date 14 Apr 1981
Regulation 91-3

COMPONENT TIMES

Position	Logbook	Description	Serial Number	Total Time	Total Cycles	TSO	CSO
1	Engine	Honeywell TFE731-2C-2B	P-89124-C	10801.4	11199	6622.2	6939
2	Engine	Honeywell TFE731-2C-2B	P-89129-C	10783.8	11187	5197.0	5572

ATA		Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (*=Adj)	Remaining Hrs/Cyc/Cal
Logbook	App		Serial Number	Section	Page				
Mfg Ref Number		Notes	Revision	Date Issued					
12-23-000.1		No. 1 Ni-Cad Emergency Power Supply Battery Inspection	AD2058 & AD2059 141870 & 135920	MM-99	3	100 Hrs	10934.7 11420	11016.3 Hrs*	26.3 Hrs
* Airframe	MAN	Notes: [25 Hour Window] [14 DAY Window]		5-10-29	07 Apr 2014	3 MOS	23 Jul 2014	17 Oct 2014*	35 Days
Mfg#: D1223000				A3					
12-23-001.1		No. 1 Ni-Cad Emergency Power Battery Discharge/Recharge	AD2058 & AD2059 141870 & 135920	MM-99	3		10548.2 11033		
* Airframe	REC	Notes: New battery pack replacement (2 packs) 9/24/13 [14 DAY Window]		5-10-29	07 Apr 2014	12 MOS	24 Sep 2013	24 Sep 2014	12 Days
Mfg#: D1223001				A3					
122150		150 Hr Learjet (Aeronca) Thrust Reverser Lube	If Installed	45-10000	1	150 Hrs	10888.3 11374	11038.3Hrs	48.3 Hrs
* Airframe	REC	Notes: Integrated with LH & RH Aeronca TR 150HR Periodic Inspections (78-30-086-A1.1 & A1.2) [50 Hour Window] [CUSTOM FREQUENCY]		78-30-00	27 Aug 1999		20 Jun 2014		
Mfg#: N/A				TR 78-12					
051040		Complete Phase D Inspection		MM-99	2	2400 Hrs	8677.9 8961	11077.9Hrs	87.9 Hrs
* Airframe	MAN	Notes: [25 Hour Window] [14 DAY Window]		5-10-00	07 Apr 2014	96 MOS	15 Jul 2010	15 Jul 2018	46 Mos
Mfg#: N/A				A3					
27-10-009.1		Aileron Center Sector Control Cable Life Limit	2300003-17	MM-99	9	2400 Hrs	8677.9 8961	11077.9Hrs	87.9 Hrs
* Airframe	MAN	Notes:		5-11-00	07 Apr 2014		15 Jul 2010		
Mfg#: F2710009				A3					
27-10-009.4		LH Aileron Inboard Wing Control Cable Life Limit	2300003-78	MM-99	9	2400 Hrs	8677.9 8961	11077.9Hrs	87.9 Hrs
* Airframe	MAN	Notes:		5-11-00	07 Apr 2014		15 Jul 2010		
Mfg#: F2710009				A3					

ATA		Description	Part Number	Source Document		Frequency (* = Initial)	Complied With Hrs/Cyc/Date	Next Due (* = Adj)	Remaining Hrs/Cyc/Cal
Logbook	App		Serial Number	Section	Page				
Mfg Ref Number		Notes		Revision	Date Issued				
27-10-009.5		RH Aileron Inboard Wing Control Cable Life Limit	2300003-77, -272	MM-99		2400 Hrs	8677.9	11077.9Hrs	87.9 Hrs
*	Airframe	MAN		5-11-00	9		8961		
	Mfg#: F2710009		Notes:	A3	07 Apr 2014		15 Jul 2010		
27-10-009.6		Aileron LH Fuselage Control Cable Life Limit	2300003-245	MM-99		2400 Hrs	8677.9	11077.9Hrs	87.9 Hrs
*	Airframe	MAN		5-11-00	9		8961		
	Mfg#: F2710009		Notes:	A3	07 Apr 2014		15 Jul 2010		
27-10-009.7		Aileron RH Fuselage Control Cable Life Limit	2300003-246	MM-99		2400 Hrs	8677.9	11077.9Hrs	87.9 Hrs
*	Airframe	MAN		5-11-00	9		8961		
	Mfg#: F2710009		Notes:	A3	07 Apr 2014		15 Jul 2010		
27-10-009.8		Aileron Control Wheel LH Interconnect Cable Life Limit	2300003-231	MM-99		2400 Hrs	8677.9	11077.9Hrs	87.9 Hrs
*	Airframe	MAN		5-11-00	9		8961		
	Mfg#: F2710009		Notes:	A3	07 Apr 2014		15 Jul 2010		
27-10-009.9		Aileron Control Wheel RH Interconnect Cable Life Limit	2300003-229	MM-99		2400 Hrs	8677.9	11077.9Hrs	87.9 Hrs
*	Airframe	MAN		5-11-00	9		8961		
	Mfg#: F2710009		Notes:	A3	07 Apr 2014		15 Jul 2010		
27-50-044.1		LH Flap Cam Follower Bearings Inspection		MM-99		1200 Hrs	9874.7	11077.9 Hrs*	87.9 Hrs
*	Airframe	MAN		5-10-29	12		10322		
	Mfg#: H2750044		Notes: [25 Hour Window]	A3	07 Apr 2014		27 Jun 2012		
27-50-044.2		RH Flap Cam Follower Bearings Inspection		MM-99		1200 Hrs	9874.7	11077.9 Hrs*	87.9 Hrs
*	Airframe	MAN		5-10-29	12		10322		
	Mfg#: H2750044		Notes: [25 Hour Window]	A3	07 Apr 2014		27 Jun 2012		
32-44-024		Right Gear Down Safety Switch & Anti-Skid Electrical Contact		MM-99		1200 Hrs	9874.7	11077.9 Hrs*	87.9 Hrs
*	Airframe	MAN		5-10-029	8		10322		
	Mfg#: R3244024		Notes: [300 Initial Hour Req.] [25 Hour Window]	A3	07 Apr 2014		27 Jun 2012		
57-50-046.1		LH Flap Track Support Fitting Inspection		MM-99		1200 Hrs	9874.7	11077.9 Hrs*	87.9 Hrs
*	Airframe	MAN		5-10-29	13		10322		
	Mfg#: H5750046		Notes: [25 Hour Window]	A3	07 Apr 2014		27 Jun 2012		
57-50-046.2		RH Flap Track Support Fitting Inspection		MM-99		1200 Hrs	9874.7	11077.9 Hrs*	87.9 Hrs
*	Airframe	MAN		5-10-29	13		10322		
	Mfg#: H5750046		Notes: [25 Hour Window]	A3	07 Apr 2014		27 Jun 2012		
24-31-017		Battery Cables & Receptacles Connector Inspection		MM-99		300 Hrs	10782.3	11082.3Hrs	92.3 Hrs
*	Airframe	MAN		5-10-29	4		11250		
	Mfg#: H2431017		Notes: [25 Hour Window]	A3	07 Apr 2014		17 Mar 2014		
720005		150 to 250 Hour Engine Routine Periodic Inspection		72-02-01		150 Hrs	10728.5	10878.5Hrs	94.7 Hrs
*	Engine 2	MAN		72-00-00, Tab	611		11129		
	Mfg#: N/A		Notes: [100 Hour Window]	10	26 Sep 2008		23 Jul 2014		
78-30-086-A1.1		LH Aeronca Thrust Reverser 150 Hr Periodic Inspection		45-1000		150 Hrs	10934.7	11084.7Hrs	94.7 Hrs
*	Airframe	MAN		78-30-00	2		11420		
	Mfg#: P7830086		Notes: [50 Hour Window]	TR 78-13	17 Sep 2004		23 Jul 2014		

ATA		Description	Part Number	Source Document		Frequency (**=Initial)	Complied With Hrs/Cyc/Date	Next Due (*Adj)	Remaining Hrs/Cyc/Cal
Logbook	App		Serial Number	Section	Page				
Mfg Ref Number		Notes	Revision	Date Issued					
78-30-086-A1.2		RH Aeronca Thrust Reverser 150 Hr		45-1000		150 Hrs	10934.7	11084.7Hrs	94.7 Hrs
*	Airframe	MAN	Periodic Inspection	78-30-00	2		11420		
	Mfg#: P7830086		Notes: [50 Hour Window]	TR 78-13	17 Sep 2004		23 Jul 2014		
720005		150 to 250 Hour Engine Routine Periodic		72-02-01		150 Hrs	10774.1	10924.1Hrs	122.7 Hrs
	Engine 1	MAN	Inspection	72-00-00, Tab	611		11174		
	Mfg#: N/A		Notes: [100 Hour Window]	10	26 Sep 2008		23 Jul 2014		
257002		Raisbeck Aft Stowage Locker 12 Month		95-120			10616.3		
*	Airframe	MAN	Inspection		2		11111		
	Mfg#: N/A		Notes: [14 DAY Window]	B	01 Dec 1998	12 MOS	05 Dec 2013	05 Dec 2014	84 Days
982748.1		SB 35/36-27-48 R1 Control Column	Kit 2381602-801	SB 35/36-27-48		600**	0.0	11179.0 Hrs*	189.0 Hrs
	Airframe	REC	Assembly Replacement				0		
			Notes: [600 Initial Hour Req.] [48 MOS Initial Req.]	1	21 Oct 2013	48MOS**		21 Oct 2017	37 Mos